



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 06/11/2025

Shift: C

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-----------------|-----------------------------------------------|----------------------------------------------------|----------------------|----------------------|-------------------------------------------------|
| 1 | OHP | CO 29 | OLR acted | reset | 22:45:00 | 22:55:00 | |
| 2 | OHP | CO 26 | olr acted | reset | 04:10:00 | 04:15:00 | |
| 3 | OHP | CO 5 | olr acted 2 times due to material on conveyor | reset | 04:00:00 | 04:35:00 | |
| 4 | OHP | co 34 | olr acted,jamming | reset | 23:25:00 | 01:00:00 | 4 times |
| 5 | CHP | CC 125 | olr acted | reset | 23:55:00 | 00:05:00 | |
| 6 | CHP | CC 37 SCR7 | B/C OLR ACTED,due to jamming | reset | 00:20:00 | 01:40:00 | 3 times |
| 7 | CHP | CC 104 SCR 9 | slew and b/w not working,oil level low | checked electrical side all ok,informed mechanical | 01:00:00 | 01:11:00 | continue oil leakage not arrested by mechanical |
| 8 | CHP | CC 48 | zss acted,cage flipped | cage adjusted | 04:00:00 | 04:15:00 | |
| 9 | CHP | CC 38 SCR6 | LT not working found drive tripped | reset | 04:50:00 | 05:50:00 | |
| 10 | WT | OT 3 | D1 tripped in encoder fault | reset | 00:40:00 23:40:00 | 00:45:00 23:45:00 | |
| 11 | WT | OT 1 | d1 tripped in pgf1 fault | reset | 01:10:00 | 01:15:00 | |