



वी.एस.पी.  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 01/11/2025

Shift: B

Incharge(s): Amit Roy

SI No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-29	Reported tripped.	OLR acted.Reset done(4times)	17:00:00 17:45:00 18:30:00 20:10:00	17:10:00 17:50:00 18:35:00 20:20:00	
2	OHP	CO-26	Reported tripped	OLR acted.Reset done(5 times)	17:45:00 19:30:00 20:00:00 21:00:00 21:45:00	18:00:00 19:40:00 20:10:00 21:10:00 21:55:00	
3	OHP	BRC on CO-30	B/W-2 reported tripped	MCCB tripped due to motor TB bolts sheared and touching body	21:00:00	22:30:00	TB fixing is going on
4	CHP	CC-52	Reported tripped	OLR acted.Reset done(2 times)	14:05:00 16:05:00	14:10:00 16:10:00	
5	CHP	CC-54	Reported tripped	OLR acted.Reset done	16:45:00	16:50:00	
6	CHP	CC-35	D/E CJD not working	CJD cable got cut. cable joint done and tested okay	15:15:00	15:30:00	
7	CHP	CC-35	Reported tripped	OLR acted.Reset done	15:30:00	15:40:00	
8	CHP	Cc-104 SCr-9	All drives not working	ACB tripped.Made on	18:55:00	19:10:00	
9	CHP	Cc-38 SCR-6	LT not working	M1,2 tripped due to track jamming.MADE on and tested okay	20:20:00	20:40:00	
10	CHP	Cc-35 SCR-3	LT,slew not working	Drive tripped for LT.Slew chamber jamming found.Drive reset done	21:00:00	21:15:00	For slew informed to operation



वी.एस.पी.  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 01/11/2025

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
11	CHP	Cc-35	Reported tripped.	OLR acted.Reset done	21:15:00	21:20:00	
12	CHP	Cc-125	Reported tripped	OLR acted.Reset done	21:25:00	21:30:00	
13	WT	OC-1A	Reported tripped	OLR acted.Reset done	21:25:00	21:30:00	
14	IOSA	HVMCC-6	I/C-1,2 showing tripped	DC failed.Restored and tested okay.(2times)	14:50:00 16:20:00	15:10:00 16:45:00	