

RASTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 25/05/2025 Incharge(s): V Balaji Naik,G Eswara Rao Shift: A

SI No	Area	Equipment	Problem	Action	From	То	Remarks
1	ОНР	co 26	tripped on olr	reset done	10:45:00	11:00:00	
2	OHP	brc on co 30	bw 1 not running/olr acted	reset done	11:00:00	11:15:00	
3	OHP	brc on co 33m	hydrolic pump not running/oil level low	inform to ope. and mech	12:45:00	13:00:00	/
4	OHP	CO29	over load trip	Reset done	14:00:00	14:00:00	02.35pm to 02.40pm
5	OHP	WOBR on CO26	LT not working found PCRD over tension limit acted	Released then ok	14:00:00	14:00:00	05.30pm to 05.50pm
6	СНР	CC131	Over load trip Scraper deflector plate jam(more than 5 times)	Reset done	09:16:00	09:20:00	Scraper plate removal is planned after shut down by mechanical
7	CHP	CC115	Running imspection defect rectified	One phase incoming cable carbon formed, cable damaged(R phase) MCCB module replaced with 250A	08:15:00	08:35:00	
8	CHP	cc 125	tripped on olr	reset done	12:50:00	13:00:00	
9	CHP	CC114	Tripped due to over load	Reset done	06:50:00	07:00:00	
10	CHP	SCR1 on CC36	Yard motor ZSS kept in ckt, luffing area jamm cleared	Luffing limit kept in ckt	06:30:00	06:40:00	
11	CHP	SCR4 on CC33	LT not working found PCRD cable over tension acted	Tension released then ok	07:00:00	12:07:00	Page 1/2



RASTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 25/05/2025

Shift: A

Incharge(s): V Balaji Naik,G Eswara Rao

SI No	Area	Equipment	Problem	Action	From	То	Remarks
12	CHP	S1 on CC34	LT not working found PCRD over tension acted	Tension released then ok	07:20:00	07:30:00	
13	CHP	CC41	Motor stopping frequently found CJB cable damaged	Spare cable replaced then ok	09:00:00	09:20:00	
14	CHP	CC125	Motor over load MPD trip	Reset done	12:50:00	12:55:00	
15	CHP	CC44	Motor not running MPD trip in over load due to over feeding	Reset done	13:00:00	13:10:00	
16	CHP	CC125	over trip	Reset done	14:00:00	14:00:00	04.47pm to 04.55pm
17	WT	OP9	Not moving found reached to no power zone at parking area	By providing jumpers bring back to power zone	09:30:00	09:45:00	Not a delay no rake