



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 07/01/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-----------------|------------------------------|--------------------|----------|----------|---------|
| 1 | OHP | Co 25 | olr acted | reset | 16:00:00 | 16:30:00 | |
| 2 | OHP | Co 38A | ZSS probe wire got cut | probe replaced | 17:50:00 | 18:00:00 | |
| 3 | CHP | CC 105 SCR10 | signal missing | LT done than ok | 15:30:00 | 15:40:00 | |
| 4 | CHP | CC 34 SCR1 | LT not working,track jammed | informed operation | 21:20:00 | 21:30:00 | |
| 5 | CHP | CC 51 | mpd tripped | reset | 21:15:00 | 21:20:00 | |
| 6 | CHP | CC 52 | mpd tripped | reset | 15:00:00 | 21:00:00 | 3 times |
| 7 | CHP | CC 131 | motor tripped 3 times | reset | 15:00:00 | 18:00:00 | |
| 8 | CHP | cc 53 | mpcb tripped due to overload | made it on | 21:30:00 | 21:40:00 | |