

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 18/09/2025

Shift: A

Incharge(s): K SANKARA RAO

| SI No | Area | Equipment | Problem | Action | From | То | Remarks |
|----------|------|-------------------|--------------------------------------------------------------|----------------------------------------------------------------|----------------------------------|----------------------------------|---------|
| 1 | OHP | CO-29 | OLR ACTED (3TIMES) | RESET DONE | 08:00:00 09:00:00 10:00:00 | 08:10:00 09:10:00 10:10:00 | |
| 2 | OHP | WOBR ON CO-26 | REPORTED SLEW NOT WORKING CHECKED OLR ACTED | RESET DONE (2TIMES) | 08:15:00 11:45:00 | 08:30:00 12:00:00 | |
| 3 | OHP | TT-3 ON BIPC-1 | REPORTED POSITION INDICATION MISSING DUE TO MATERIAL JAMMING | OPERATION REQUIREMENT POSITION INDICATION BYPASSED IN I/O RACK | 11:30:00 | 11:45:00 | |
| 4 | OHP | CC-37 SCR-7 | REPORTED SLEW NOT WORKING CHECKED AND FOUND OIL LOW LEVEL | INFORMED TO MECHANICAL | 07:10:00 | 07:20:00 | |
| 5 | CHP | CC-51 | OLR ACTED | RESET DONE | 09:40:00 | 09:45:00 | |
| 6 | CHP | CC-40 S-1 | LUFF NOT WORKING CHECKED MPCB TRIP | MADE ON | 07:10:00 | 07:40:00 | |
| 7 | CHP | CC-31 SCR-4 | REPORTED SLEW NOT WORKING CHECKED AND FOUND POWER MCCB TRIP | MADE ON THAN OK | 07:15:00 | 07:30:00 | |
| 8 | CHP | CC-36 SCR-1 | REPORTED PCRD CABLE FALLEN DOWN | PCRD CABLE PROPER LAYING WAS DONE | 09:45:00 | 10:00:00 | |
| 9 | WT | OT-1 | DRIVE -1 TRIP | RESET DONE | 12:20:00 | 12:25:00 | |