



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 21/01/2026

Shift: B

Incharge(s): Nagendra Midde

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-------------------------------|-----------------------------|--------------------------------|----------------------|----------------------|-----------------------------|
| 1 | OHP | TBS ON CO 20 LEFT LUFT UP | LIMIT SWITCH PROBLEM | ADJUSTED | 14:30:00 | 14:45:00 | LIMIT SWITCH TO BE REPLACED |
| 2 | OHP | BRC ON CO 30 B/C NOT RIUNNING | EMERGENCY STOP NOT RELEASED | RELEASED THEN OK | 21:35:00 | 21:45:00 | |
| 3 | CHP | CC 131 | OLR ACTED | RESET | 15:35:00 20:05:00 | 15:40:00 20:20:00 | |
| 4 | CHP | CC 51 | FEEDING CONV OLR ACTED | RESET | 19:20:00 | 19:25:00 | |
| 5 | CHP | CC 114 | OLR ACTED | RESET | 19:15:00 | 19:25:00 | |
| 6 | CHP | SCR 6 ON CC 39 | LT DRIVE TRIPPED | RESET | 16:05:00 | 16:15:00 | |
| 7 | CHP | CC 28 POSITION NOT COMING | FUSE BLOWN | REPLACED | 18:45:00 | 18:55:00 | |
| 8 | IOSA | OC 37A | BRS NOT RESETTING | SENSOR ADJUSTMENT DONE THEN OK | 20:40:00 | 20:50:00 | |