

RASTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 30/04/2025

Shift: C

Incharge(s): Lal Singh

| SI No | Area | Equipment | Problem | Action | From | То | Remarks |
|----------|------|----------------|---|--|----------------------|----------------------|---------|
| 1 | OHP | CO-35 | TRIPPED ON OLR | RESET DONE | 22:25:00 23:30:00 | 22:30:00 23:40:00 | |
| 2 | OHP | CO-8A BRC | CT NOT WORKING | DRIVE TRIPPED ON OL RESET DONE | 00:10:00 | 00:30:00 | |
| 3 | CHP | CC-34 SCR-2 | SLEW NOT WORKING | OPERATOR DOING SLEW WITH LUFFING EXPLAINED | 02:50:00 | 03:05:00 | |
| 4 | CHP | CC-40 SCR-6 | SLEW NOT WORKING | MATERIAL JAMMING INFORMED OPERATION FOR CLEANING | 04:00:00 | 04:20:00 | |
| 5 | CHP | CC-52 | STOPPED ON ZSS | DUE TO MATERIAL OVERLOAD | 01:35:00 | 01:40:00 | |
| 6 | CHP | CC 113 | STOPPING ON CC-52 OVERLOAD | CC-52 OVERLOAD BIT IS SHOWING HING EVEN WHEN CC-52 IN OFF CONDITION BIT REMOVED IN IO RACK | 00:30:00 | 00:40:00 | |
| 7 | CHP | CC-53 | STOPPED ON BELT SWAY | ALL SWITCHES ARE OK AND NO OFF-CENTERING BYPASSED IN 10 RACK | 00:20:00 | 00:35:00 | |
| 8 | CHP | CC-114 | TRIPPED ON OLR | RESET DONE | 05:45:00 | 05:55:00 | |
| 9 | CHP | CC-58 | TRIPPED ON OLR | RESET DONE | 22:30:00 | 22:50:00 | |
| 10 | CHP | CC-117 | TRIPPED ON OLR | RESET DONE | 04:05:00 | 04:25:00 | |
| 11 | CHP | CC-51 | STOPPED ON ZSS | BELT LOOSE INFORMED MECHANICAL AND OPERATION | 02:30:00 | 02:45:00 | |
| 12 | WT | OT-5 | TOP CLAMP NOT CLOSING COMPLETELY IN ON TIME | VERTICAL PRESSER SETTING CHANGED FROM 38 TO 40 | 22:45:00 | 23:00:00 | |