Shift: C



CHP

6

13

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 14/07/2025

Incharge(s): Saurabh Kumar Yadav,K SANKARA RAO

CC 40 SCR | LT not working, drive trips in overload

| SI No | Area | Equipment | Problem | Action | From | То | Remarks |
|----------|------|---------------------|---|--|----------|----------|---------|
| 1 | OHP | CO 26 | OLR ACTED(2TIMES) | RESET | 04:00:00 | 04:30:00 | |
| 2 | OHP | TT 4 | TT NOT MOVING MPCB TRIP | RESET | 04:45:00 | 05:00:00 | |
| 3 | OHP | RSCO 1A | STOPPING ON ZS ZS PROBE LOOSE | TIGHTEN THAN OK | 05:15:00 | 05:40:00 | |
| 4 | OHP | CO 13 (C) DRIVE | OLR ACTED | RESET | 05:30:00 | 05:45:00 | |
| 5 | OHP | WOBR ON CO 6A | B/W STOPPING OIL LOW LEVEL SHOWING | IN FORMED TO MECH | 04:15:00 | 04:40:00 | |
| 6 | OHP | TBS ON CO | LT NOT TAKING PLACE CHECKED SELECTOR IN LOCAL MODE | KEPT IN REMOTE THAN OK | 05:30:00 | 05:40:00 | |
| 7 | CHP | CC 51A | OLR ACTED(2TIMES) | RESET | 03:40:00 | 03:55:00 | |
| 8 | CHP | CC 103 ON TT | LT NOT TAKING PLACE CHKED OLD JOINT OPEN | TEMPRARY JOINT DONE | 02:10:00 | 03:00:00 | |
| 9 | CHP | OLD CCR | PLC room ac mcb trips | made it on | 22:25:00 | 22:35:00 | |
| 10 | CHP | CC 105 | yard conveyor not healthy,shutdown tag was there | shutdown normalize | 23:30:00 | 23:37:00 | |
| 11 | CHP | SCR 10 on CC 105 | B/C not running,mcb trips not getting on,earth fault, | field wire removed than mcb hold,than contactor not getting on even command is reached upto X1-8,9loop given from x1 8 to x1-23 and x1-9 to x1 -25 and clearance given | 00:20:00 | 02:45:00 | |
| 12 | CHP | CC 33 scr 4 | LT not working, drive trips in overload | reset | 02:00:00 | 02:10:00 | |

reset

01:25:00

01:35:00