



वी.एस.पी.  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 15/11/2025

Shift: A

Incharge(s): K SANKARA RAO

| SI No | Area | Equipment      | Problem  | Action  | From                 | To                   | Remarks |
|-------|------|----------------|--|---|----------------------|----------------------|---------|
| 1     | OHP  | CO-26          | OLR ACTED (2TIMES)   | RESET DONE  | 07:30:00<br>10:10:00 | 07:40:00<br>10:20:00 |         |
| 2     | OHP  | RSCO-10A       | REPORTED STOPPING IN ZSS FOUND PROBE CHECK NUT LOOSE                     | PROBE CHECK NUT TIGHT THAN OK                         | 09:50:00             | 10:00:00             |         |
| 3     | OHP  | BRC ON CO-30   | B/C TRIPPED ON OLR   | RESET DONE  | 09:15:00             | 09:25:00             |         |
| 4     | OHP  | CO-58          | REPORTED STOPPING ON ZSS PROBE DIRECT                                    | ZSS PROBE REPLACED WITH NEW PROBE THAN OK             | 12:45:00             | 13:40:00             |         |
| 5     | CHP  | CC-29 TO CC-31 | POSITION INDICATION NOT SHOWING AT I/O RACK FIELD WIRE REMOVED CONDITION | FIELD WIRE CONNECTED THAN OK                          | 06:50:00             | 07:00:00             |         |
| 6     | CHP  | CC-54          | OLR ACTED (4TIMES)   | RESET DONE  | 07:00:00             | 12:00:00             |         |
| 7     | CHP  | CC-117         | OLR ACTED  | RESET DONE  | 06:00:00             | 06:10:00             |         |
| 8     | CHP  | CC-131         | OLR ACTED  | RESET DONE  | 11:40:00             | 11:45:00             |         |
| 9     | CHP  | BC STREAM      | REPORTED NOT HEALTHY FOUND LC-19 I/C-1 TRIP DUE TO EARTH FAULT           | FAULT ISOLATED I/C CHARGED THAN OK                    | 12:00:00             | 12:15:00             |         |
| 10    | CHP  | CC-31 SCR-4    | B/C NOT RUNNING FOUND SELECTION PROBLEM                                  | SELECTOR SWITCH KEPT CORRECT POSITION THAN OK         | 06:40:00             | 06:50:00             |         |
| 11    | CHP  | CC-33 SCR-5    | PCRD CABLE FELL DOWN DUE TO SINGLE PHASE                                 | OUT GOING CONNECTION TIGHT THAN CABLE LAYING WAS DONE | 07:50:00             | 08:10:00             |         |
| 12    | CHP  | CC-104 SCR-9   | SLEW NOT WORKING FOUND RELAY STUCK UP                                    | RELEASED THAN OK                                      | 08:05:00<br>09:40:00 | 08:15:00<br>09:55:00 |         |
| 13    | CHP  | CC-112 SCR-8   | SLEW NOT WORKING LIMIT ACTED DUE TO JAMMING                              | AFTER CLEANING MATERIAL LIMIT RELEASE THAN OK         | 09:20:00             | 09:30:00             |         |