



वी.एस.पी.  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 31/01/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment     | Problem   | Action                                     | From     | To       | Remarks |
|-------|------|---------------|---|--|----------|----------|---------|
| 1     | OHP  | wobr on co 25 | luffing not taking place,d4 no contact loose connection | checked full luff ckt,loose wire tightened | 15:30:00 | 15:58:00 |         |
| 2     | OHP  | CO 26         | olr acted   | reset                                      | 15:50:00 | 15:59:00 |         |
| 3     | CHP  | CC 51         | MPD tripped 2 times                                     | reset                                      | 19:30:00 | 19:35:00 |         |
| 4     | CHP  | CC 131        | olr acted   | reset                                      | 20:35:00 | 20:40:00 |         |
| 5     | CHP  | CC 12         | brs problem,brs sensor misalignment                     | sensor adjusted                            | 15:30:00 | 15:40:00 |         |
| 6     | CHP  | CC 201        | motor olr acted   | reset                                      | 14:25:00 | 14:35:00 |         |
| 7     | CHP  | CC 40 SCR2    | slew not working,limit acted                            | released                                   | 16:20:00 | 16:35:00 |         |
| 8     | WT   | OP5           | no power,pusher @dead zone                              | pusher brought to power zone               | 16:00:00 | 16:20:00 |         |