

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 15/10/2025

Shift: A

Incharge(s): Saurabh Kumar Yadav

| SI No | Area | Equipment | Problem | Action | From | То | Remarks |
|----------|------|-----------------|---|--------------------|----------|----------|---------|
| 1 | OHP | co 26 | olr acted | reset | 10:50:00 | 11:00:00 | |
| 2 | OHP | BRC on CO 31 | bc not running,zss acted,zss cable got cut | cable jointed | 11:30:00 | 11:45:00 | |
| 3 | CHP | CC 112 SCR8 | b/w not running,power cable got cut near slew chamber | cable jointed | 07:45:00 | 09:00:00 | |
| 4 | CHP | CC 35 SCR3 | b/c not running,olr acted ,mpr acted | reset | 07:45:00 | 07:55:00 | |
| 5 | CHP | CC 38 SCR6 | B/W not running,b/w stucked in coal | informed operation | 10:25:00 | 10:40:00 | |
| 6 | CHP | CC 35 SCR3 | slew and Lt not working | wrong complaint | 10:50:00 | 11:10:00 | |
| 7 | CHP | CC 201 | motor tripped in olr | reset | 10:00:00 | 10:10:00 | |
| 8 | CHP | CC 203 | olr acted | reset | 12:30:00 | 12:35:00 | |
| 9 | WT | OC 1A(b) | olr acted | reset | 08:30:00 | 08:35:00 | |
| 10 | WT | OT 1 | D1 tripped in pgf1 fault | reset | 08:55:00 | 09:00:00 | |
| 11 | WT | CO 3(B) | olr acted | reset | 11:05:00 | 11:10:00 | |