



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 28/05/2026

Area: OHP

Equipment	Job
stacking stream inspection	field safety devices bypasses checking is under progress.
1-141LC3	sump pump is checked and de watering is done.
JH-15, 38b h/e,37a h/e	spare motors cleaning and megger values recorded.
co-50 h/e hoist	ppm is done.
co-50,51,68	field devices ppm is done.
wobr-1 on co-26	bc and bw motors inspection is done.
wobr-3 on co-29	LT motor M3 motor tb was missing, canopy provided. BW and bc motor inspection is done.
co-77,84,86,34,33m ; co-50,51 belt and carriage ; crusher-3	motor and panel side ppm is done.
yard conveyors. co-19,7a,20,24	BSS inspection is done, found to be in circuit. co-19 bss switch chp side handle is missing, fixed back in place. co-5a BSS circuit to be checked.