



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 27/05/2026

Incharge(s): G Eswara Rao

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR ON CO 29	BW NOT RUNNING/WINDING LEAD GOT EARTH FAULT AND HALF OF THE LEADS MELTD.	WINDING LEAD STRAIGHT FERUL LUGGING DONE THEN TESTDED OK	09:50:00	12:30:00	
2	OHP	WOBR ON CO 29	LUFFING OLR ACTING FEQUENTLY	MOTOR and OLR CHECKED FOUND OK	09:50:00	10:15:00	
3	CHP	CC 7,8,9	REPORTED RED/INCOMMER. 1 TRIPPRED AT 1- 14 LC 21	CHECKED AND FOUND CC 8 MOTOR GOT BURNT./IN FORM TO G SHIFT .	07:45:00	08:30:00	
4	CHP	CC 201	TRIPPED ON OLR	RESET DONE	07:30:00	07:40:00	
5	CHP	CC 29	ZSS IN BYPASSED	ZSS KEPT IN CKT	10:00:00	10:25:00	
6	CHP	CC 24 C/D	FESTOON CABLE GOT DAMAGED	RE-JOINTED ,THEN TESTD OK	10:00:00	10:20:00	
7	CHP	SCR 3 ON CC37	NO POWER/BREAKER TRIPPED AT LBDS 4 and 5	CHECKING IS GOING ON	13:35:00	14:00:00	