



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 30/07/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co 25	olr acted	reset	23:00:00	23:05:00	
2	OHP	BRC on CO 32	oil cooler tripped after pump made on,in I/O rack zss1 and 2 bypass from oil cooler heathy	bypass oil cooler FB and ZSS 1 and 2 in program and given clearance @1,30 am but operator was not available.i/o rack zss bit high removed from oil cooler and oil cooler and cooler run FB kept in ckt	00:35:00	01:30:00	zss 1 and 2 bypassed in program
3	OHP	cc 37 scr3	slew right not working,jamming	informed to operation	23:20:00	23:30:00	
4	CHP	CC 104 scr9	slew not working,mccb tripped	mccb made on	23:30:00	23:40:00	
5	CHP	CC 32	motor mpd tripped	reset	01:50:00	01:55:00	
6	CHP	CC 31 scr1	LT and slew not working,OT and slew limit acted	released	05:05:00	05:15:00	
7	CHP	CC 52	mpd acted	reset	01:15:00	01:20:00	3 times
8	WT	OAF 2A	not running, jamming	informed operation	05:20:00	05:30:00	
9	WT	OT 5	not running,LS1 and 2,emergency acted in i/h side	emergency PB released,LS1 and 2 bypassed	05:40:00	05:50:00	