



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 16/07/2026

Shift: B

Incharge(s): Nagendra Midde

| Sl No | Area | Equipment      | Problem                                                               | Action                    | From     | To       | Remarks  |
|-------|------|----------------|-----------------------------------------------------------------------|---------------------------|----------|----------|----------|
| 1     | OHP  | co 31          | ZSS ACTING/                                                           | PROBE AND MODULE REPLACED | 20:30:00 | 21:00:00 | NO DELAY |
| 2     | OHP  | WOBR ON CO 29  | LT NOT TAKING PLACE/CONTROL MCB TRIPED                                | MCB MADE ON               | 16:20:00 | 16:25:00 |          |
| 3     | CHP  | SCR 7 ON CC40  | BC NOT RUNNING/30 DEGREE LIMIT ACTED DUE TO CABLE GOT CUT NEAR MAGNET | RE JOINT DONE             | 14:15:00 | 14:50:00 |          |
| 4     | CHP  | SCR 1 ON CC 31 | BC NOT RUNNING/30DEGREE LIMIT ACTED                                   | RESET DONE                | 14:35:00 | 14:50:00 |          |
| 5     | CHP  | SCR 2 ON CC32  | SLEW NOT TAKING PLACE/JAMMING                                         | INFORM TO OPERATION       | 15:50:00 | 16:00:00 |          |
| 6     | CHP  | SCR 6 ON CC 38 | LT NOT TAKING PLACE/IN LOCAL MODE                                     | KEPT IN REMOTE MODE       | 20:05:00 | 20:10:00 |          |
| 7     | CHP  | CC 215         | ZSS ACTING/DIDNT FOUND ANY PROBLEM                                    | CLEARANCE                 | 21:30:00 | 21:40:00 |          |
| 8     | CHP  | CC 28          | TT FLAP GATE TRIPPED ON OLR                                           | RESET DONE                | 14:20:00 | 14:30:00 |          |
| 9     | CHP  | CC 201         | TRIPPED ON OLR                                                        | RESET DONE                | 18:45:00 | 18:55:00 |          |
| 10    | CHP  | CC 203         | TRIPPED ON OLR                                                        | RESET DONE                | 14:35:00 | 14:45:00 |          |
| 11    | WT   | OT 3           | DRIVE 1 TRIPPED ON ENCODER FAULT                                      | RESET DONE                | 16:30:00 | 16:30:00 |          |