



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 13/07/2026

Incharge(s): Amit Roy

Shift: C

| Sl No | Area | Equipment       | Problem                         | Action                                                                           | From                             | To                               | Remarks               |
|-------|------|-----------------|---------------------------------|----------------------------------------------------------------------------------|----------------------------------|----------------------------------|-----------------------|
| 1     | OHP  | CO-29           | Reported tripped                | OLR acted.Reset done                                                             | 01:20:00                         | 01:30:00                         |                       |
| 2     | OHP  | Cr-3A           | Reported permissive not healthy | Lubrication return oil flow red.Reset done at panel near crusher and tested okay | 00:30:00                         | 00:40:00                         |                       |
| 3     | OHP  | VF-1A           | Reported not running            | Checked and found CS acted.                                                      | 01:34:00                         | 01:45:00                         | Informed to operation |
| 4     | CHP  | CC-125          | Reported tripped                | OLR acted.Reset done(3 times)                                                    | 00:22:00<br>01:40:00<br>03:25:00 | 00:27:00<br>01:45:00<br>03:30:00 |                       |
| 5     | CHP  | RG-2 F/G        | Reported not moving             | OLR acted.Reset done                                                             | 04:20:00                         | 04:25:00                         |                       |
| 6     | CHP  | CC-26 on CC-22A | Signal missing                  | Checked and found TT placement not proper.Properly placed and tested okay        | 23:20:00                         | 23:30:00                         |                       |
| 7     | CHP  | CC-14           | Reported tripped                | OLR acted.Reset done                                                             | 04:00:00                         | 04:10:00                         |                       |
| 8     | WT   | OT-3            | Reported not rotating           | D-1 tripped on encoder 43 fault.Reset done                                       | 02:55:00                         | 03:00:00                         |                       |