



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 09/10/2026

Incharge(s): Amit Roy

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-8	ZSS acting	Wire loose at MCC panel.Tightened and tested okay	01:30:00	02:00:00	
2	OHP	TT-3 on CO-7A	Position bit missing	Bypassed	23:00:00	23:10:00	TO be checked
3	OHP	CC-28 TT	Reported not moving	Power made on and tested okay	22:30:00	22:40:00	
4	OHP	CO-26	Reported tripped	OLR acted.Reset done	00:10:00	00:20:00	
5	OHP	CO-25	Reported tripped	OLR acted.Reset done	00:20:00	00:25:00	
6	OHP	BRC on CO-28	B/W-1 not rotating	MCCB tripping immediately.Motor and cable checked and found okay.MCCB changed but still tripping	02:50:00	06:30:00	Checking is going on
7	OHP	CO-25	Reported tripped	MPD tripping on Over current fault.Reset done(4 times)	03:00:00	04:45:00	Informed operation to check belt and load
8	OHP	WOBR on CO-29	Reported LT not taking place	PCRD tension acted.Released	03:43:00	03:53:00	
9	CHP	CC-51	MPD tripped	Reset done(3 times)	00:40:00	02:00:00	
10	CHP	CC-131	Reported tripped	OLR acted.Reset done	04:50:00	04:55:00	
11	CHP	CC-22 (C/D)	Reported tripped	OLR acted.Reset done	22:20:00	22:30:00	
12	CHP	CC-31 SCR-1	Slewing not taking place	Wrong complaint	00:55:00	01:10:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 09/10/2026

Incharge(s): Amit Roy

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
13	CHP	CC-33 SCR-2	LT not working	Pcrd cable found laying on ground.PCRD contactor R-ph opened.loop given and winding done	03:40:00	04:00:00	Contactor to be changed