



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 06/05/2026

Shift: A

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-29	OLR ACTED	RESET DONE	06:20:00	06:25:00	
2	OHP	WOBR ON CO-26	LT NOT TAKING PLACE FOUND PCRD O/T ACTED	RELEASED THAN OK	06:45:00	07:00:00	
3	OHP	WOBR ON CO-26	B/W NOT RUNNING	FAULT RESET IN OPERATOR CABIN	08:00:00	08:25:00	
4	OHP	BRC ON CO-28	REPORTED ALL DRIVES ARE NOT RUNNING FOUND INTER LOCK PANEL MCB OFF CONDITION	MADE ON	06:30:00	06:45:00	
5	OHP	BRC ON CO-34	B/W-2 NOT RUNNING PENDING FROM NIGHT SHIFT TIMER CONTACT PROBLEM	BY PASSED	06:30:00	07:50:00	
6	CHP	CC-51	MPD TRIP (FEEDING CONVEYOR STOP)	RESET DONE	11:55:00	11:58:00	
7	CHP	CC-131	OLR ACTED	RESET DONE	09:30:00	09:35:00	
8	CHP	TIS ON CC-113	OLR ACTED	RESET DONE	06:50:00	07:00:00	
9	CHP	CC-23 (C) DRIVE	NOT MOVE FOUND JB TO MOTOR POWER CABLE B- PHASE JOINT OPEN	RE-JOINT DONE THAN OK	07:30:00	09:00:00	
10	WT	CO-4 (C) DRIVE	OLR ACTED	RESET DONE	06:50:00	07:00:00	