



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/06/2026

Incharge(s): Saurabh Kumar Yadav

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	wobr on co 6A	yard zss interlock bit not coming,zss cage nut and bolt missing,probe too	New probe and ZSS installed and checked	11:35:00	12:25:00	
2	OHP	CO 26	OLR acted	reset	08:05:00	08:10:00	2 times
3	CHP	CC 31 SCR1	luff not working,due to OLr	reset	08:20:00	08:30:00	
4	CHP	cc 54	olr acted	reset	09:10:00	09:20:00	