



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 21/08/2026

Incharge(s): Lal Singh

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	wbr-2 on co-29	LT NOT WORKING in VFD .. M3 MPCB TRIPPED	RESET DONE	06:25:00	06:35:00	
2	OHP	WBR-1 ON CO -26	LT AND LUFF NOT WORKING	CONTROL WAS IN OFF ... MADE ON	12:10:00	12:20:00	
3	OHP	brc-2 on co-30	Bridge conveyor MPR terminal burnt,	replaced with spare one and trail run is taken	11:00:00	12:00:00	
4	OHP	CO-13 C	OLR ACTED	RESET DONE	11:55:00	12:10:00	
5	OHP	CO-50	NOT STARTING	WRONG ROUTE	12:50:00	13:05:00	
6	OHP	co-13 BD	OLT ACTED	RESET DONE	12:00:00	12:15:00	
7	CHP	SCR-7 CC-40	SIGNAL MISSING	STOPPED FROM CPP	13:50:00	14:10:00	INFORMED B SHIFT
8	CHP	CC-52	MPD TRIPPED 2 TIMES	RESET DONE	11:30:00	13:10:00	
9	CHP	CC-51	MPD TRIPPED 3 TIMES	RESET	11:35:00	13:20:00	
10	WT	OT-4	CLAMPING NOT WORKING	NO ELECTRICAL PROBLEM	07:00:00	07:30:00	
11	WT	EOT	MAIN CONTACTOR LUG MELTED	RECTIFIED	11:00:00	12:00:00	
12	WT	OT-5	CLAMPING DONE NOT COMING ... TIPPLER NOT ROTATING	PRESSER NOT REACHING UP TO SET POINT INFORMED OPERATION	13:20:00	13:25:00	