



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL GENERAL SHIFT REPORT**

Date: 13/05/2026

Area: OHP

| Equipment                                           | Job                                                                                                                                                                                                 |
|-----------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| tbs-2 on co-20                                      | running inspection is done. and defect list made ready                                                                                                                                              |
| repair bay HT transformer                           | The tank base leakage welding job is in progress.                                                                                                                                                   |
| cr-1,2,3 level                                      | lighting is improved.                                                                                                                                                                               |
| lc-6 sump pump                                      | pipeline fixing done and connected to sump pump outlet.                                                                                                                                             |
| 1-141lc3,lc4 ground floor ; 1-14lc7 ; om-15,om-16   | housekeeping is done.                                                                                                                                                                               |
| om-16,24,1-15lc2,1-141lc3,1-141lc4 ground floor RIO | ario ppm is done.                                                                                                                                                                                   |
| co-8,11                                             | panel side ppm is done.                                                                                                                                                                             |
| co-76r,18                                           | panel and motor side ppm is done.                                                                                                                                                                   |
| co-14 pullchord                                     | cable got rub due to return idler missing, joint done after fixing of idlers and kept back in circuit.                                                                                              |
| brc-1 on co-28                                      | Bridge conveyor motor checked, current checked, found normal, LT speed is increased from 100 rpm to 150 rpm on operation requirement. BC ZSS preparation is under progress. Panels Blowing is done. |
| brc-3 on co-33m                                     | shifted from co-33m to co-34                                                                                                                                                                        |