



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 05/05/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment    | Problem                                                                        | Action                                                                                                                                                                           | From     | To       | Remarks             |
|-------|------|--------------|--------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------|---------------------|
| 1     | OHP  | co 29        | olr acted                                                                      | reset                                                                                                                                                                            | 22:00:00 | 22:10:00 |                     |
| 2     | OHP  | wobr on Co6A | slew not working,cp acted                                                      | informed mechanical                                                                                                                                                              | 01:00:00 | 01:10:00 |                     |
| 3     | OHP  | BRC on CO 28 | no power,power is there,LT not working, main interlock mcb was in off          | brake fuse replaced,mcb made on                                                                                                                                                  | 05:55:00 | 06:30:00 |                     |
| 4     | OHP  | brc on co 34 | B/W 2 not running,timer problem,loose connection                               | panel is full of dust tracing of cable is impossible,T1,T2,T3,T4 identification problem,T1 timer control wire loose connection tightened,Bw 2 bypassed given temporary clearance | 05:25:00 | 06:30:00 | refereed to a shift |
| 5     | OHP  | CO 36        | olr acted                                                                      | reset                                                                                                                                                                            | 00:40:00 | 00:50:00 |                     |
| 6     | CHP  | CC 39 SCR7   | LT not working,drive tripped                                                   | reset                                                                                                                                                                            | 22:30:00 | 22:40:00 |                     |
| 7     | CHP  | cc 39 scr 7  | b/c not running in stacking mode,slew limit problem,magnet switch cable opened | first bypassed than magnet cable rejoined                                                                                                                                        | 22:40:00 | 23:00:00 |                     |
| 8     | CHP  | CC 37 scr 3  | LT not working,m3 tripped                                                      | made it on                                                                                                                                                                       | 04:53:00 | 05:00:00 |                     |
| 9     | CHP  | CC 51        | mpd acted                                                                      | reset                                                                                                                                                                            | 23:40:00 | 23:45:00 | 2 times             |
| 10    | CHP  | CC 58 TT     | power cable got cut,position sensor not coming                                 | rejointed power cable,tt position sensor bypassed in I/o rack                                                                                                                    | 01:10:00 | 03:00:00 |                     |