



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 25/09/2026

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-29	Reported tripped	OLR acted.Reset done	14:30:00	14:35:00	
2	OHP	CO-6A	BRS acted	Bypass wire loose at electronic BRS.Looped tightened	16:20:00	16:30:00	BRS sensor replaced and kept in line @7.30pm
3	OHP	CO-25	Reported tripped	OLR acted.Reset done	16:30:00	16:50:00	
4	OHP	TBS on CO-7A	LT not taking place	PCRD tension acted.Released and tested okay	16:50:00	17:10:00	
5	OHP	TBS on CO-21	LT not taking place	M-3 olr acted due to gearbox stuck in material.Reset done	17:10:00	17:30:00	
6	OHP	RSCO-6A(C/D)	Reported tripped	OLR acted.Reset done(2 times)	18:20:00	18:45:00	
7	OHP	VS-2	Reported tripped	OLR acted.Reset done	19:25:00	19:30:00	
8	OHP	VS-2A	Reported tripped	OLR acted.Reset done	21:40:00	21:50:00	
9	OHP	CO-26	Reported tripped	OLR acted.Reset done	17:30:00	17:40:00	
10	OHP	TBS on CO-21	LT not taking place	Drive tripped.Reset done	17:58:00	18:22:00	
11	OHP	BRC on CO-8A	Reported hydraulic pump not running	High temperature found.Oil cooler feeder tripped.Made on and temperature cooled down and tested okay	19:40:00	20:21:00	
12	OHP	TBS on CO-5A	LT not taking place	PCRD overlapping in drum	20:40:00	20:50:00	Informed to mechanical



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 25/09/2026

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
13	CHP	CC-52	MPD tripped	Reset done	19:45:00 20:00:00	19:50:00 20:05:00	
14	IOSA	CO-14A	Reported healthy stop	RF PC acted.Reset done	16:20:00	16:30:00	