



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 06/08/2026

Shift: A

Incharge(s): P Venkat Kiran,P Venkat Kiran

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co-26	olr acted 2 times	reset done	08:00:00 08:30:00	08:10:00 08:40:00	
2	OHP	brc-3 on co-34	It not taking place	pcrd overtension acted	07:50:00	08:05:00	released
3	OHP	wbr-2 on co-29	It not taking place	Drive tripped on OL due to track jamming	09:00:00	09:00:00	reset done and informed agency
4	CHP	CC 104	BRS ACTED	Moisture entered into module.Hot blowing done and kept in ckt	06:45:00	07:00:00	
5	CHP	CC 104	ZSS problem	Sensor replaced	08:55:00	09:15:00	
6	CHP	PROC-B TO A	Observed GPL is stopping due to communication issues	established redundant processors communication via new switched and testing done.	13:30:00	14:30:00	
7	WT	co-3	zss acted	material stuck in cage.	09:20:00	09:45:00	cleared material and trail run is taken