



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 16/08/2026

Incharge(s): Amit Roy,P Venkat Kiran,P Venkat Kiran

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-29	Reported tripped	OLR acted.Reset done	17:30:00	17:40:00	
2	OHP	CO-26	Reported tripped	OLR acted.Reset done	17:55:00	18:00:00	
3	OHP	TBS on Co-7A	Chute vibrator not working	Power cable got cut at TB.Reconnected and tested okay	15:00:00	15:30:00	Cable lugging to be done
4	CHP	CC-28	FG tripped	MPCB tripped.Made on	19:25:00	19:35:00	
5	CHP	CC-52	MDP tripped	Reset done	21:40:00	21:45:00	
6	WT	AF-4	Reported tripped	Control MCB tripped.Made on	14:45:00	14:50:00	
7	WT	OP-5	Reported not moving	D6 motor kept out of line.coil connection removed	17:35:00	17:45:00	TO be checked and to be kept in line