



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 05/07/2026

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS on CO-5A	LT not taking place	M-2 tripped.Reset done	16:00:00	16:15:00	
2	OHP	WOBR on CO-29	Luffing not taking place	OLR acted.Reset done	17:05:00	17:20:00	
3	OHP	VS-1A	Reported not healthy	E-PB acted	19:20:00	19:25:00	Informed to operation
4	OHP	TBS on CO-7A	LT not taking place	Wrong complaint	20:55:00	21:10:00	
5	OHP	VF-10A	Chute vibrator not working	MPCB tripped.Made on	15:00:00	15:15:00	
6	CHP	CC-213 SCR-9	Lt not taking place	PB acted panel.Released and tested okay	17:50:00	18:05:00	
7	CHP	CC-213 SCR-9	Reported signal not coming	CPP side material request not given	17:50:00	18:05:00	
8	CHP	Cc-32	Reported tripped	OLR acted.Reset done	21:15:00	21:20:00	
9	CHP	CC-107	Reported tripped	OLR acted.Reset done	21:20:00	21:25:00	
10	CHP	CC-31	Reported tripped	OLR acted.Reset done	21:30:00	21:35:00	
11	CHP	CC-201	Reported tripped	OLR acted.Reset done	20:00:00	20:05:00	
12	CHP	CC-205	Reported tripped	OLR acted.Reset done	20:05:00	20:10:00	
13	CHP	CC-28	F/G tripped	OLR acted.Reset done	16:00:00	16:30:00	
14	WT	AF-2	Reported tripped	Drive tripped on over current.Reset done	21:20:00	21:30:00	
15	WT	OT-1	Reported not rotating	NO electrical problem	17:10:00	18:10:00	