



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 06/07/2026

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	Co-58	Reported tripped	OLR acted.Reset done	15:05:00 16:30:00	15:20:00 16:45:00	
2	OHP	WOBR on Co-29	Luffing not working	OLR Acted.Reset done	17:10:00	17:25:00	
3	OHP	BRC on CO-30	CJD acting	Due to heavy vibration	18:55:00	19:25:00	Informed to operation
4	OHP	BRC on CO-30	B/W-1 no rotating	Fluid coupling resonant plate damaged	20:10:00	20:20:00	Informed to operation
5	OHP	BRC on Co-32	LT not working	Operator cabin reset done	21:05:00	21:15:00	
6	CHP	Cc-54	Reported tripped	OLR acted.Reset done	17:36:00	17:40:00	
7	CHP	Cc-213 SCR-9	LT not taking place	PCRD overtension acted.Released	18:40:00	18:50:00	
8	CHP	Cc-105 SCR-10	Operator stopped machine due to no lighting at cabin	MCB tripped.Made on	19:05:00	19:20:00	
9	CHP	Cc-111	ZSS acting	No problem found	19:50:00	20:00:00	
10	WT	OT-3	Reported tripped	D1 tripped on encoder fault.Reset done	19:30:00	19:35:00	
11	IOSA	OC-14A	Reported tripped	DMPR tripped due to snub pulley jamming.Reset done	17:40:00	17:50:00	