



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 01/08/2026

Incharge(s): M Kailash

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS ON CO-7A	No Drives running. ACB found tripped	Made on and tested OK	22:15:00	22:30:00	
2	OHP	BRC ON CO-31	Lt not taking place. Found Drive tripped on SC fault. M1 MPCB burnt.	M1 Motor circuit isolated and given clearance	00:55:00	02:00:00	Motor to be checked and MPCB to be changed. 16 to 32A
3	OHP	CO-26	Tripped on overload	Reset done	04:30:00	04:40:00	
4	IOSA	OC-2A	Chute sensor malfunctioning. Checked Electrical side OK.	Informed to instrumentation. Sensor side adjustment done	02:40:00	03:15:00	