



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 20/07/2026

Incharge(s): Amit Roy

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-26	Reported tripped	OLR acted.Reset done	23:30:00	23:40:00	
2	OHP	CO-5A	Reported BRS not healthy	Checked and found no supply at module.Bypassed.After made to tun zss acting.Checked and found no supply at module.F-19 tripped at MCC panel.BRS cable earth fault found.high removed at CJB and tested okay	23:30:00	00:15:00	BRS earth fault to be checked and to be kept in line
3	OHP	BRC on CO-28	B/C not running	OLR acted.Reset done	00:35:00 01:40:00	00:40:00 01:50:00	
4	OHP	CO-21	Reported BRS not resetting	Checked and found belt pieces	03:15:00	03:30:00	Informed to opration
5	CHP	CC-42	Reported not running	While giving command no faults are generated and its not taking command	05:45:00	06:30:00	To be checked