



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 11/06/2026

Incharge(s): Saurabh Kumar Yadav

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR on co 25	b/c not running,olr i/c y phase cable melted	olr reset,Y pahse reconnected	09:40:00	10:00:00	
2	OHP	TBS on CO 24	LT not working,reclaiming height interlock problem	luff done than ok	12:10:00	12:20:00	
3	CHP	RSCO-10A(C)	olr acted	reset	11:15:00	11:30:00	
4	CHP	CC 38 SCR5	conveyor stopped in ZSS,safety pin not intact,probe wire got cut	probe reconnected,pin intact	06:45:00	07:00:00	
5	CHP	CC 38 SCR5	LT not working,M1 tripped	reset	09:35:00	09:40:00	
6	CHP	CC 51	mpd acted	reset	10:15:00	10:20:00	2 times