



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 10/06/2026

Incharge(s): K SANKARA RAO

Shift: A

| Sl No | Area | Equipment    | Problem                                               | Action                                  | From     | To       | Remarks |
|-------|------|--------------|-------------------------------------------------------|-----------------------------------------|----------|----------|---------|
| 1     | OHP  | TBS ON CO-7A | REPORTED L/B NOT RUNNING FOUND BOTH B/C OFF CONDITION | MADE ON THAN OK                         | 11:15:00 | 11:25:00 |         |
| 2     | CHP  | CC-203       | OLR ACTED                                             | RESET DONE                              | 11:05:00 | 11:10:00 |         |
| 3     | CHP  | CC-51        | MPD TRIP (FEEDING CONVEYOR)                           | RESET DONE                              | 09:45:00 | 09:50:00 |         |
| 4     | CHP  | CC-31,SCR-1  | B/C SIGNAL MISSING                                    | LT FWD DONE THAN OK                     | 07:10:00 | 07:20:00 |         |
| 5     | CHP  | CC-31,SCR-1  | SIGNAL MISSING                                        | PLC POWER AND CONTROL RE-CYCLED THAN OK | 07:50:00 | 08:00:00 |         |
| 6     | CHP  | CC-40, SCR-7 | LT NOT TAKING PLACE                                   | WRONG COMPLAINT                         | 09:20:00 | 09:25:00 |         |
| 7     | WT   | OP-2         | DRIVE-3 OLR ACTED                                     | RESET DONE                              | 12:00:00 | 12:15:00 |         |