



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 07/08/2026

Shift: C

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-25	Reported tripping immediately on command	Checked and found DMPR tripped on unbalanced current fault. Checked and found motor winding lug got cut. Lugging done and motor tested okay	23:10:00	02:00:00	
2	OHP	CO-26	Reported tripped	OLR acted. Reset done	01:05:00 02:55:00	01:10:00 03:00:00	
3	OHP	BRC on CO-28	B/C not running	OLR acted. Reset done	02:15:00	02:30:00	
4	OHP	CO-29	Reported tripped	OLR acted. Reset done(5 times)	01:45:00	05:55:00	
5	OHP	CC-27A	ZSS acting	checked and tested okay	05:40:00	06:00:00	
6	CHP	CC-29 on CC-31	Position bit missing	Sensor damaged. Bypassed	22:15:00	22:25:00	To be replaced
7	CHP	CC-51	MPD tripped	Reset done(2 times)	01:10:00	01:15:00	
8	CHP	CC-51	MPD tested	Feeding conveyor stopped. Reset Done	03:50:00	03:55:00	
9	CHP	CC-54	MPD tripped	Reset done(2 times)	04:35:00 04:45:00	04:40:00 04:50:00	
10	CHP	CC-33 SCR-2	B/C not running	ZSS cage got stuck. Made free	22:50:00	23:15:00	
11	WT	AF-3	Reported not running in local	Selector switch stuck. Made free	02:00:00	02:15:00	
12	WT	SCO-1A	ZSS acted	Target got disturbed. Adjusted and tested okay	04:00:00	04:10:00	