



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 30/04/2026

Incharge(s): G Eswara Rao

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 26	TRIPPED ON OLR	RESET DONE/2TIMES	08:55:00	09:00:00	
2	OHP	TBS ON CO5A	BC NOT RUNNING/CHUTE JAMMING	INFORM TO OPERATION	07:00:00	07:30:00	
3	OHP	WOBR ON CO 26	BC NOT RUNNING/OLR ACTED	RESET DONE	12:15:00	12:25:00	
4	CHP	cc 27A	C/S WAS BYPASSED	KEPT IN CKT.	10:20:00	10:25:00	
5	CHP	CC103	TT POSITION SIGNAL REQUEST ON CC 106	HIGH GIVEN AT I/O RACK	10:35:00	10:40:00	
6	CHP	CC 15	BRS ACTED/CONTROL CABLE CAME OUT FROM PLUG	CABLE INSERT THEN OK	11:00:00	11:15:00	
7	CHP	SCR 3 ON CC37	NO POWER/PCRD CABLE GOT CUT DUE TO CABLE FALLEN ON TRACK BECAUSE OF PCRD CHAIN GOT OPEN(MOTOR TO DRUM)	in form to DNW	09:40:00	10:00:00	ONE HT FUSE BLOWN
8	CHP	R1 ON CC36	NO POWER/	BREAKER TRIPPED BECAUSE OF SCR 3CABLE PROBLEM/BREAKER MADE ON AT 1-12 LBDS 4 AND 5	10:10:00	10:25:00	