RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 04/11/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS on CO-20	LT not taking place	M-4 tripped duet to track jamming.Reset done	11:20:00	11:30:00	Informed to operation
2	OHP	BRC on CO-28	Lt not taking place	Drive tripped.Made on	12:20:00	12:35:00	
3	OHP	CO-26	Reported tripped	OLR acted.Reset done	12:55:00	13:05:00	
4	OHP	CO-10A	Reported tripped	OLR acted.Reset done	06:20:00	06:30:00	
5	CHP	CC-54	Reported tripped	OLR acted.Reset done	12:20:00	12:25:00	
6	CHP	CC-29 TT	Reported Lt not taking place	OLR acted.Reset done	06:40:00	06:50:00	
7	CHP	Cc-13	Reported ZSS acting	Due to material jamming.After clearing tested okay	08:20:00	08:40:00	
8	CHP	R-1 on CC-36	B/C not running	Boom conveyor got folded at skirt rubber	13:40:00	13:50:00	No electrical
9	WT	OP-5	Reported not moving	Breaker tripped at LC while coupling and again tripped while after moving forward.No problem found.Breaker made on and tested okay	07:40:00 09:15:00	08:10:00 09:20:00	
10	WT	CO-4(C/D)	Reported tripped	OLR acted.Reset done	09:20:00	09:30:00	
11	IOSA	OC-7B	Reported BRS acting frequently	Material on decksheet.After cleaning BRS reset done	09:15:00	09:40:00	