



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 16/09/2026

Shift: C

Incharge(s): Amit Roy,Lal Singh

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	VF-21	Reported tripped	Found sinter plant side motor submerged in material due to chute hole.Power kept off and informed to mechanical	23:45:00	01:39:00	After mechanical rectification power made on and tested okay
2	OHP	CO-10A	Reported tripped	OLR acted.Reset done	00:53:00 04:05:00	00:59:00 04:10:00	
3	OHP	RSCO-6A(C/D)	Reported tripped	OLR Acted.Reset done	04:35:00	05:00:00	
4	OHP	CO-29	Reported tripped	OLR Acted.Reset done	03:35:00 05:15:00	03:40:00 05:20:00	
5	OHP	WOBR on CO-25	Luffing not taking place	Wrong complaint	03:35:00	04:10:00	
6	OHP	TBS on CO-22	Lt not taking place	M-3 motor to gearbox coupling problem.	04:40:00	05:00:00	Informed to mechanical
7	CHP	CC-51	Belt sway not healthy	Kept in bypass due to requirement	22:50:00	23:00:00	Switch problem identified. To be rectified
8	CHP	CC-131	Reported tripped	OLR acted.Reset done	01:55:00	02:00:00	
9	CHP	SCR-9 on CC-104	B/W not rotating	Found also slewing not taking place.Pump MCCB off.Made on and tested okay	04:20:00	04:30:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 16/09/2026

Shift: C

Incharge(s): Amit Roy,Lal Singh

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
10	WT	OP-9	Reported not moving	Phase loss between column no.83,84.Forward reverse done in local mode and tested okay	00:55:00	01:15:00	