वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 01/11/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	wobr on co 29	LT and luffing not working,M2 olr acted	reset	16:55:00	17:10:00	
2	OHP	CR1	showing red,mpr olr acted	reset	18:05:00	18:10:00	
3	OHP	VF 10A	olr acted	reset	20:00:00	20:15:00	
4	CHP	CC 40 scr7	BC not running,signal problem,signal gone 2 times	LT done than ok but again signal problem came	19:00:00	19:30:00	
5	CHP	CC 51	mpd acted	reset	15:35:00	15:40:00	
6	CHP	CC 131	motor tripped 2 times	reset	14:35:00	14:40:00	
7	WT	OP9	no communication,	POE power recycle done in OP9	20:15:00	20:35:00	
8	WT	OP2	no movement,power ok	pusher @parking zone,middle phase power not coming,@col 4 from parking zone to trolley line temporary bolt tightened than power holding	20:28:00	21:20:00	