वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 11/11/2026

Shift: A

Incharge(s): Lal Singh

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS ON COI -21	R- LUFF OLR ACTED	RESET DONE	12:58:00	13:10:00	
2	OHP	TBS ON CO-7A	LT NOT WORKING	PCRD OT RELEASED THEN TESTED OK	13:10:00	13:20:00	
3	OHP	BRC ON CO-32	ALL DRIVES NOT WORKING	ACB OFF ... MADE ON THEN OK	13:25:00	13:35:00	
4	OHP	BRC ON CO-28	BC NOT RUNNING	EM STOP NOT COMING ... BYPASSED IN PANEL AND TESTED	11:10:00	11:55:00	TO BE KEPT IN CKT
5	OHP	WBR ON CO-26	LUFF EM ACTED	LUFF DOWN AND LIMIT KEPT IN CKT AND TESTED	12:15:00	12:30:00	
6	OHP	CO-22 TBS	NO POWER ... PCRD CABLE PROBLEM	RECTIFIED BY DNW	09:20:00	12:40:00	
7	CHP	CC-203 FG	MPCB TRIPPED	MADE ON AND TESTED	11:30:00	11:40:00	
8	CHP	CC-131	MPD TRIPPED 5 TIMES	RESET DONE	11:00:00	13:00:00	
9	CHP	CC-131	TRIPPED	RESET DONE	12:40:00	12:45:00	
10	CHP	CC-108	BRS NOT RESETTING	SENSOR CLEANING AND ALIGNMENT DONE THEN RESET	09:22:00	09:35:00	
11	CHP	CC-32 SCR-5	LT NOT WORKING ... PCRD OT ACTED	RELEASED	10:55:00	11:10:00	
12	CHP	CC-40 SCR-7	SIGNAL MISSING	POWER RECYCLED THEN OK	13:15:00	13:30:00	
13	WT	OT-5	NOT ROTATING	BREAK RECTIFIER PROBLEM ... REPLACED AND TESTED	06:00:00	07:10:00	