



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 14/06/2026

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-25	Reported tripped	OLR acted.Reset done	14:10:00 17:20:00 18:55:00	14:20:00 17:30:00 19:05:00	
2	OHP	WOBR on CO-6A	B/C not running	Yard interlock ZSS probe damaged.Replaced and tested okay	16:40:00	17:05:00	
3	OHP	WOBR on CO-29	Lt not taking place	PCRD tension acted.Mechanical guide problem	17:35:00	17:50:00	Informed to mechanical
4	OHP	BRC on CO-33M	CT not taking place	Wrong complaint	20:05:00	20:20:00	
5	OHP	BRC on CO-8A	Reported Low tank temp acted	Loop found fallen down.Loop tightened and tested okay	14:20:00	14:30:00	
6	CHP	CC-51	MPD tripped	Reset done	20:50:00	20:55:00	
7	CHP	Cc-131	Reported tripped	OLR acted.Reset done	19:20:00	19:25:00	
8	CHP	All yard conveyors Red	BRS and BSS acted	Checked and found LC-14 I/O rack 110V supply MCB tripped. Made on and tested okay	14:40:00 21:40:00	14:55:00 21:50:00	
9	CHP	CC-47	ZSS acted	Loose connection at module.Tightened and tested okay	18:40:00	18:55:00	
10	CHP	CC-31 SCR-1	Luffing not taking place	OLR acted.Reset done	18:50:00	19:15:00	
11	CHP	CC-40 SCR-7	No operations taking place	ACB tripped.Made on	20:30:00	20:45:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 14/06/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	WT	AF-6	Not running pending from A shift	Motor replaced and made to run and found same tripping on over current while running	14:00:00	17:00:00	Informed to mechanical