



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 18/09/2026

Shift: C

Incharge(s): Amit Roy,K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-29	OLR ACTED (2TIMES)	RESET DONE	00:25:00 04:10:00	00:35:00 04:15:00	
2	OHP	VS-3A	OLR ACTED	RESET DONE	00:55:00	01:05:00	
3	OHP	TBS ON CO-22	REPORTED ALL DRIVES NOT WORKING FOUND CONTROL MCB TRIP DUE TO EARTH FAULT	CONTROL MCB MADE ON EARTH FAULT RECTIFIED THAN OK	01:30:00	01:50:00	
4	OHP	CO-10A	OLR ACTED (2TIMES)	RESET DONE	02:10:00 05:00:00	02:20:00 05:10:00	
5	OHP	TT-1A ON CO-3A	REPORTED TT NOT MOVING FOUND PCRD SLIP RING IN SIDE CABLE PROBLEM	WORK IS GOING ON	01:00:00	06:30:00	
6	CHP	CC-131	OLR ACTED	RESET DONE	01:15:00	01:20:00	
7	CHP	CC-54	OLR ACTED	RESET DONE	02:10:00	02:15:00	
8	CHP	CC-112 SCR-8	REPORTED B/C NOT RUNNING FOUND TUL JAMMING INFORMED TO OPERATION	AFTER JAMMING CLEAR THAN OK	00:50:00	01:05:00	
9	CHP	CC-40 SCR-7	B/C OLR ACTED	RESET DONE	02:40:00	03:00:00	