



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 02/06/2026

Incharge(s): Amit Roy

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-11	ZSS acting	Probe damaged.Replaced and tested okay	04:00:00	04:30:00	
2	OHP	BRC on CO-30	CT not working	CT chain broken	02:45:00	03:00:00	Informed to mechanical
3	OHP	BRC on CO-32	LT not taking place	PCRD tension acted.Released	04:55:00	05:15:00	
4	OHP	BRC on CO-32	Reported B/W-2 not rotating on load	No electrical problem	03:30:00	03:45:00	Informed to mechanical
5	CHP	CC-104 SCR-6	LT not taking place	M-1.2 tripped due to track jamming.Reset done	04:15:00	04:25:00	Informed to operation
6	WT	OT-3	Reported tripped	Drive tripped on fault code-7.Reset done	01:00:00 23:45:00	01:05:00 23:50:00	