



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 01/05/2026

Shift: A

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co 26	olr acted	reset	07:05:00	07:15:00	4 times
2	OHP	wobr on co 25	slewing not working,drive tripped	reset	06:35:00	06:50:00	
3	OHP	BRC on CO 32	bc not running,emergency acted near e house	emergency released	07:20:00	07:40:00	
4	OHP	BRC on CO 28	bc not running,olr acted	reset	09:45:00	09:55:00	
5	CHP	cc 31	slew not working,drive tripped	reset	06:50:00	07:00:00	
6	CHP	CC 33 SCR2	Lt not working,wrong complaint	checked found all ok	07:40:00	07:50:00	
7	CHP	CC 33 SCR2	slew not working,left limit acted due to jamming	informed operation	07:50:00	08:00:00	
8	CHP	CC 107	olr atced	reset	09:00:00	09:05:00	
9	CHP	CC 31,32 and 33 yard conveyor	not healthy,acb tripped in LC17	made it on	11:05:00	11:15:00	
10	CHP	C C 51	mpd acted	reset	09:05:00	09:10:00	
11	WT	OP7	no fwd movement,ls1 and 2 acted in OT4	ls1 and 2 bypass	08:45:00	08:58:00	
12	WT	OP 4	no movement,D2 olr acted @ coupling time	reset	10:10:00	10:20:00	