



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 13/05/2026

Shift: A

Incharge(s): G Eswara Rao

| Sl No | Area | Equipment     | Problem                                                | Action                    | From                 | To                   | Remarks                |
|-------|------|---------------|--------------------------------------------------------|---------------------------|----------------------|----------------------|------------------------|
| 1     | OHP  | co 16         | tripped on olr /5 times                                | reset done                | 08:50:00             | 09:10:00             |                        |
| 2     | OHP  | CO 26         | TRIPPED ON OLR                                         | RESET DONE                | 09:40:00             | 09:50:00             |                        |
| 3     | OHP  | BRC ON CO 32  | LT NOT TAKING PLACE                                    | RESET DONE AT CABIN       | 10:40:00             | 10:50:00             |                        |
| 4     | CHP  | CC 33         | 110 KW NEW MOTOR REPLACED                              | CLEARANCE GIVEN AT 1130AM | 06:30:00             | 11:30:00             | MOTOR BURNT IN C SHIFT |
| 5     | CHP  | CC 44         | TRIPPED ON OLR/2 TIMES                                 | RESET DONE                | 07:40:00             | 07:45:00             |                        |
| 6     | CHP  | CC 125        | TRIPPED ON OLR                                         | RESET DONE                | 08:00:00             | 08:05:00             |                        |
| 7     | CHP  | SCR 3 ON CC37 | SLEW NOT TAKING PLACE/SLEW AREA JAMMING                | INFORM TO OPERATION       | 10:50:00             | 11:00:00             |                        |
| 8     | CHP  | CC 51         | MPD TRIPPED ON OLR                                     | RESET DONE 2 TIMES        | 08:30:00<br>10:40:00 | 08:40:00<br>10:50:00 | FEEDING C ONV.STOP PED |
| 9     | CHP  | TIS ON CC 52  | FEED BACK MISSING/TIS ZSS PROBE PLATE BEND GAP DISTRUB | GAPADJUSTED THEN OK       | 12:30:00             | 13:00:00             |                        |
| 10    | CHP  | CC 201        | TRIPPED ON OLR                                         | RESET DONE                | 13:35:00             | 13:40:00             |                        |
| 11    | CHP  | CC 203        | TRIPPED ON OLR                                         | RESET DONE                | 13:25:00             | 13:30:00             |                        |