



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/05/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC on CO 34	b/c not running,empg PB operated near operator cabin	EMG PB released	00:45:00	01:00:00	
2	CHP	scr 10 on cc 105	no power, 3 no's fuse blown in I/O,i/c 2 tripped in LC2,coupler @ drive end having problem	i/c made on, coupler and slip ring side opened,megger done one phase zero value	23:00:00	00:20:00	loop provide d,informed MVN murty sir,DNW will come in A shift
3	CHP	CC 106 s2	slew not working,jamming in slew area	informed operation	02:35:00	02:45:00	
4	CHP	CC 33 SCR2	b/c is stopping,communication problem	yard interlock zss kept in ckt and probe replaced	02:40:00	03:15:00	
5	CHP	CC 104 scr 6	slew not working,right side,coal jamming	informed operation	02:40:00	02:55:00	
6	CHP	CC 38 SCR5	b/c not running,olr acted	reset	03:00:00	03:15:00	
7	CHP	LC 19	fdr1 tripped	made it on	04:50:00	05:10:00	
8	CHP	CC 51	mpd acted	reset	02:50:00	02:55:00	
9	CHP	CC 58 TT	signal not coming,fuse blown	fuse replaced	22:30:00	23:30:00	kept in ckt
10	WT	OP4	slow moving,sensor problem	sensor bypassed	00:30:00	00:50:00	