



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 19/05/2026

Incharge(s): G Eswara Rao

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 26	TRIPPED ON OLR	RESET DONE	08:30:00	08:45:00	
2	OHP	CO 50	TRIPPED ON OLR	RESET DONE	09:15:00	09:25:00	
3	OHP	RCO 6A	TRIPPED ON OLR	RESET DONE	09:50:00	10:00:00	
4	CHP	CC 54	TRIPPED ON OLR	RESET DONE	12:35:00	12:40:00	
5	CHP	CC 131	TRIPPED ON OLR	RESET DONE	08:15:00	08:25:00	
6	CHP	CC 131	TRIPPED ON OLR	RESET DONE	06:15:00	06:20:00	
7	CHP	SCR 2 ON CC33	SLEW NOT TAKING PLACE	WRONG COMPLAINT	06:50:00	07:00:00	
8	CHP	CC 125	TRIPPED ON OLR	RESET DONE	08:35:00	08:40:00	
9	CHP	SCR 1 ON CC31	B/W NOT RUNNING/OLR ACTED	RESET DONE	13:20:00	13:25:00	
10	WT	OT 4	F/ REVERSE NOT TAKING PLACE/ZERO POSITIONAL SIGNAL NOT GETTING TO CABIN	ZSS PROBE GAP ADJUSTED THEN OK	07:30:00	07:40:00	
11	WT	CO 3	TRIPPED ON MPCB 2 TIMES	MADE ON	13:30:00	13:40:00	DUE TO JAMMING