



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 07/08/2026

Shift: A

Incharge(s): P Venkat Kiran,P Venkat Kiran

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co-26	olr acted	heavy material on belt	06:30:00	07:15:00	
2	OHP	wbr-4 on co-6a	lt not taking place	m5 LT motor MPCB was tripping, removed it and restored LT operation	07:20:00	08:00:00	
3	OHP	co-65	brs bypassed on operation request	bypassed at cjb, and kept under observation.	12:00:00	12:10:00	
4	OHP	tbs-5 on co-24	lbc was stopping on zss	probe problem, zss probe replaced and checked.	07:00:00	07:35:00	
5	OHP	co-29	olr acted twice	reset done	08:30:00 09:20:00	08:50:00 09:30:00	
6	OHP	brc-3 on co-34	LT was not taking place	vfd was tripping on earth fault, M1 disconnected and restored LT operation	08:30:00	08:45:00	
7	OHP	brc-3 on co-34	LT not taking place	PCRD over tension acted.	11:15:00	11:30:00	released
8	OHP	brc-4 on co-8a	bw1 stopping on zss	zss bypass loose at io rack.	12:15:00	12:30:00	
9	OHP	CO 13 DC	MPCB tripping due to fistoon cable insulation damaged	Properly Insulated then ok	10:40:00	11:00:00	
10	CHP	SCR 1 on CC 31 Slew	Coal Jamming	After Cleaning ok	07:20:00	07:40:00	
11	WT	cp-1	no power , pending from C shift	column no. 10, insulator punctured.	06:00:00	07:00:00	insulator removed and packing provided
12	IOSA	oc-27a	BRS frequently acting	brs bypassed on operation requirement	11:50:00	12:00:00	