



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 26/08/2026

Incharge(s): G Eswara Rao

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CR .3A LUB RICATION PUMP	NOT GETTING RESET/ 1 PHASE INSULATION DAMAGED AT MOTOR TB DUE TO LOOSE AND MPCB TRIPPED	MPCB MADE ON AFTER RE-TERMINATION .	17:50:00	18:20:00	
2	OHP	co 26	olr acted	reset	19:30:00	19:40:00	
3	OHP	wobr on co 25	b/w tripped in olr	reset	21:20:00	21:35:00	
4	CHP	cc 51	mpd acted,R phase lug got at motor TB	lug replaced and given clearace	15:40:00	17:00:00	
5	CHP	CC 131	olr acted	reset	15:20:00	15:30:00	3 times
6	CHP	CC 58	tripped in curt sp fault	reset	18:30:00	18:55:00	
7	CHP	SCR 2 on CC 33	slew not working,drive tripped	reset	14:35:00	14:50:00	