



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL GENERAL SHIFT REPORT

Date: 23/06/2026

Area: OHP

Equipment	Job
co=33a hoist Brake	Fixed and alignment is done.
co=33a hoist Brake	Fixed and alignment is done.
co-50 power contactor	3TF56 replaced and trail run is taken, BPC-3 belt scale bridge blowing is done.
co-50 power contactor	3TF56 replaced and trail run is taken, BPC-3 belt scale bridge blowing is done.
Misc	Wbr-25 HT coupler space heater plug replaced and restored its working, All motors canopies checked and ensured in OHP yard.
Misc	Wbr-25 HT coupler space heater plug replaced and restored its working, All motors canopies checked and ensured in OHP yard.
TBs-6 on co-7a	Spare Thruster brakes installed at M2 and M4
TBs-6 on co-7a	Spare Thruster brakes installed at M2 and M4
110 KW spare Hydraulic motor	Coupling is made ready and fixed.
110 KW spare Hydraulic motor	Coupling is made ready and fixed.
wobr-2 on co-29 ; co-29	motor and panel side ppm is done.
wobr-2 on co-29 ; co-29	motor and panel side ppm is done.
co-17,18 gallery ; JH O-4 ; RBF level in LOCP-2, co-65 gallery, tunnel area; co-37a T/E area	lighting is improved. Circuit rectified, new lamps provided.
co-17,18 gallery ; JH O-4 ; RBF level in LOCP-2, co-65 gallery, tunnel area; co-37a T/E area	lighting is improved. Circuit rectified, new lamps provided.
co-18; co-5 side sump pump	motor and panel side ppm is done. sump pump discharge pipe was damaged informed mechanical.
co-18; co-5 side sump pump	motor and panel side ppm is done. sump pump discharge pipe was damaged informed mechanical.