



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 12/09/2026

Incharge(s): M Kailash

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	VS-2	Overload acted	Reset done	00:00:00	00:10:00	
2	CHP	CC-58	Motor MPR tripped	Reset done	22:30:00	22:50:00	
3	CHP	CC-52	MPR tripped to stop feeding conveyor	Reset done	01:40:00 22:20:00	01:45:00 22:25:00	
4	CHP	SCR-7	30 deg limit not coming. Found Limit switch cable opened near the switch	Bypassed for starting the conveyor, then jointing done properly	22:55:00	23:05:00	
5	CHP	CC-201	Overload acted	Reset done	23:25:00	23:30:00	
6	IOSA	PLC communication	Frequent communication failure between main PLC and OM-4,LC-3,LC-1, OM-1 and LC-9	power recycling done in sequence and one GBC to OFC media converter made OFF in LC-2,LC-3,OM-4,LC-1	22:20:00	01:20:00	