



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 20/09/2026

Shift: A

Incharge(s): Nagendra Midde

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR ON CO 6A	LT NOT TAKING PLACE/M4 OLR ACTED	RESET DONE /3 TIMES	09:30:00	09:40:00	
2	OHP	WOBR ON CO26	LT NOT TAKING PLACE/DRIVE TRIPPED ON OLR	RESET DONE	10:00:00	10:10:00	WHEEL NOT ROTATING AT M2
3	OHP	SB 6 -CO 42A TAILEND	NOT WORKING/AIR LEAKAGE IN PIPE LINE AT CYLINDER	INFORM TO OPE.	07:00:00	07:30:00	
4	OHP	CC 22	ZSS ACTING/PROBE CABLE JJOINT OPEN	RE-JOINTED THEN OK	09:15:00	09:30:00	
5	OHP	TBS ON CO 22	LT NOT TAKING PLACE/ BRAKE RESTENCES 2 NOS GOT MELTED	PENDING TO B SHIFT	13:00:00	14:00:00	NO DELAY
6	OHP	WOBR ON CO 26	LT NOT TAKING PLACE/M4 TRIPPED ON OLR	RESET DONE	13:40:00	13:55:00	
7	OHP	CO 26	TRIPPED ON OLR	RESET DONE	12:15:00	12:25:00	
8	OHP	CO 25	TRIPPED ON OLR	RESET DONE	10:10:00	10:20:00	
9	OHP	CO 29	TRIPPED ON OLR	RESET DONE	09:45:00	09:50:00	
10	CHP	CC 22 C/D	TRIPPED ON OLR	RESET DONE	07:15:00	07:20:00	
11	CHP	SCR 4 ON CC 111	NO DRIVES RUNNING/ SIGNAL MISSING	NEW MODEM REPLACED	07:00:00	07:15:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 20/09/2026

Incharge(s): Nagendra Midde

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	CHP	S1 ON CC 36	NO DRIVES RUNNING/FEEDER 2 TRIPPED AT 1-12 LBDS 4 and 5 AND HT FUSES 3 NOS BLOWN	CHECKED AT COUPLER AND I/O PANEL ,DIDNT FOUND ANY PROBLEM FUSES REPLACED AND HT POWER MADE ON TESTED OK	10:05:00	11:00:00	
13	CHP	SCR 8 ON CC 112	SLEW NOT TAKING PLACE/CO.NO 33 CJB 1 TO CJB2	SPARE REPLACED CORE NO.50 THEN OK	11:10:00	11:10:00	
14	WT	SCO 1A	ZSS ACTEDING/PROBE GAP DISTRUB	PROBE GAP ADJUSTED	13:10:00	13:15:00	