



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 19/09/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co 25	olr acted	reset	15:40:00	15:50:00	2 times
2	OHP	co 26	olr acted	reset	20:55:00	21:05:00	
3	OHP	co 111(b)	mpcb tripped	made on	17:54:00	18:00:00	
4	CHP	cc 111 scr 4	comm failure,modem problem	modem replaced	15:00:00	15:30:00	
5	CHP	CC 43	zss acted,loose connection	tightening done	17:25:00	17:40:00	
6	CHP	CC 111 SCR4	luff not working,up limit acted and down fuse blown in i/o rack	fuse replaced	17:50:00	18:10:00	
7	CHP	CC 32 SCR5	LT not working,pcrd chain got broken	informed mechanical	19:25:00	19:45:00	
8	CHP	cc 51	mpd acted,2 times	reset	15:00:00	15:05:00	
9	CHP	CC 52	mpd acted	reset	14:40:00	14:45:00	3 times
10	CHP	CC 54	motor tripped due to overload	reset	14:10:00	14:15:00	
11	CHP	CC 111 scr4	b/c stopped in reclaiming mode,communication problem	new modem configuration done,checking going on	21:45:00	22:10:00	
12	WT	OP 5	pending from A shift,no movement,no power,acb tripped,top pad c clamp and u clamp zss cage pin bend @ col no 69.2	power block taken for U7 to U9,c and u clamp replaced,acb made on	14:00:00	14:35:00	